

cm-07 TRMS DC/AC Clamp Meter



FEATURES

High Resolution DC 10mA, AC 1mA
True RMS
Non-contact Current Frequency Measurement



SPECIFICATION

Range	Resolution	Accuracy	Remarks
DCA 0-40A	10mA	+/- 1.0% +/- 2dgts	
DCA 0-150A	100mA	+/- 1.0% +/- 2dgts	
DCA 150-200A	100mA	- 2.2% +/- 2dgts	
DCA 200-400A	100mA	- 4.0% +/- 4dgts	
ACA 0-4A	1mA	+/- 1.5% +/- 3dgts	True RMS
ACA 0-40A	10mA	+/- 1.0% +/- 3dgts	True RMS
ACA 0-150A	100mA	+/- 1.0% +/- 3dgts	True RMS
ACA 150-200A	100mA	- 2.2% +/- 3dgts	True RMS
ACA 200-400A	100mA	- 4.0% +/- 4dgts	True RMS
Hz 0-1000KHz	0.1-100Hz	+/- 0.5% +/- 2dgts	0.1A sensitivity Auto Range

Power Source: 2 X 1.5V AA UM3 Batteries

Current Consumption: 10mA

Operating Condition: -10 °C to 50 °C at 85% max. RH